



British Medical Auctions

Ultrasound Equipment Quality Check (EQC)

Preventive Maintenance Service Report (PM Service)

SonoSite / X-Porte / 501503142

Complete

British Medical Auctions

Address: Unit 1, Sterling Centre, Eastern Road, Bracknell, RG12

Tel: +44 1252 299024

Email: enquiries@britishmedicalauctions.co.uk

Web: www.britishmedicalauctions.co.uk

Department: Service

System has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Safe

System Type:

Ultrasound System

System Manufacture:

SonoSite



Photo 1



Photo 2

Model:

X-Porte

Serial No.:

501503142



Photo 3

Year of Manufacture:

12.2015

Lot No.:

22 Radiology Auction lot 48



Photo 4

Software Level:

70.80.107.014



Photo 5




Photo 6




Photo 7




Photo 8




Photo 9




Photo 10




Photo 11

Service Code:

184

Electrical Safety Test Asset ID:

265

[25-05-2022 13_43 - sonosite SN 501503142.pdf](#)

Test Equipment No. (Electrical Safety Analyzer):
Rigel 288+
SN.:10M-0263

Calibration Due Date:
05.2023

Test Equipment No. (Ultrasound Phantom):
ATS Laboratories MODEL: 539
Multipurpose Ultrasound Phantom
SN.: 200493148

Date Performed

23 May 2022 16:51 BST

Performed By

PS

1. PRELIMINARY CHECKS

Power Up

Yes



Photo 12

Database Cleared (Including all Patient Data and Previous Owner Details)

Yes



Photo 13



Photo 14

Password Protection

No

Time and Date Check

Yes



Photo 15

Labeling

Yes



Photo 16



Photo 17

2. PHYSICAL INSPECTION

Input Power

Pass




Photo 18

Wheels and Brakes

Pass



Photo 19



Photo 20



Photo 21




Photo 22

Shielding and Covers

Pass

Console cover and Docking Station have multiple scratches.



Photo 23



Photo 24




Photo 25



Photo 26




Photo 27



Photo 28

Console

Pass



Photo 29



Photo 30




Photo 31




Photo 32




Photo 33




Photo 34




Photo 35




Photo 36



Photo 37




Photo 38

Control Panel

Pass




Photo 39

Monitor Arm

Pass



Photo 40

3. CLEANING

Monitor (CRT/LCD)

Yes



Photo 41



Photo 42

Touch screen

Yes



Photo 43



Photo 44

Console

Yes



Photo 45



Photo 46



Photo 47



Photo 48



Photo 49

Keyboard

N/A

Trackball / Optical mouse

N/A

Probe Holder

Yes



Photo 50



Photo 51



Photo 52



Photo 53

Internal Cleaning

Yes

Filter

Yes

Shielding and Covers

Yes



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58

Thermal Printer Head

Yes



Photo 59



Photo 60

4. FUNCTIONAL CHECKS

Monitor

Pass




Photo 61

Touch Panel

Pass

Little water bubbles found on touch screen but screen works and respond correctly




Photo 62




Photo 63




Photo 64




Photo 65

Console

Pass

TGC

N/A

Keyboard

N/A

B-Mode

Pass




Photo 66



Photo 67

M-Mode

Pass




Photo 68




Photo 69

C-Mode

Pass



Photo 70



Photo 71

PD-Mode

Pass



Photo 72

B/W Printer

Pass




Photo 73



Photo 74



Photo 75

5. PROBE NO.: 1

Probe Make	SonoSite
Probe Model	HFL50xp
Probe Serial Number	041K7D



Photo 76

Visual inspection

Pass




Photo 77



Photo 78




Photo 79



Photo 80




Photo 81




Photo 82

Cable

Pass



Photo 83

Lens

Pass




Photo 84

Probe Casing

Pass

Probe Casing Strain Relief

Pass

Connector

Pass

Connector Strain Relief

Pass

Lateral resolution

Pass




Photo 85

Photo 86

Photo 87

Axial resolution

Pass




Photo 88

Photo 89

Image benchmark

Pass

1. Multiple artifacts founds.




Photo 90

Photo 91

Photo 92

Photo 93

Photo 94

Photo 95




Photo 96

Photo 97

Photo 98

Photo 99

Probe passes inspection & test

No

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

No

PROBE NO.: 2

Probe Make

SonoSite

Probe Model

C60xp

Probe Serial Number

04CY3T



Photo 100

Visual inspection

Pass



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105

Cable

Pass



Photo 106



Photo 107

Lens

Pass



Photo 108



Photo 109



Photo 110

Probe Casing

Pass

Probe Casing Strain Relief

Pass

Connector

Pass

Connector Strain Relief

Pass

Lateral resolution

Pass



Photo 111

Axial resolution

Pass



Photo 112

Image benchmark

Pass



Photo 113




Photo 114




Photo 115




Photo 116




Photo 117

Probe passes inspection & test

Yes

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Yes

PROBE NO.: 3

Probe Make

SonoSite

Probe Model

P21xp

Probe Serial Number

04GXTD



Photo 118

Visual inspection

Pass



Photo 119




Photo 120




Photo 121




Photo 122



Photo 123

Cable

Pass



Photo 124



Photo 125

Lens

Pass



Photo 126



Photo 127



Photo 128

Probe Casing

Pass

Probe Casing Strain Relief

Pass

Connector

Pass

Connector Strain Relief

Pass

Lateral resolution

Pass



Photo 129

Axial resolution

Pass




Photo 130

Image benchmark

Pass




Photo 131




Photo 132

Probe passes inspection & test

Yes

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Yes

6. SUMMARY

This service has been completed in accordance with our quality procedure.
If you have any questions or concerns, please contact us on
+44 1252 299024
or email: enquiries@britishmedicalauctions.co.uk to discuss further.


System has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Safe

Date Performed:

24 May 2022 14:20 BST

Service Engineer Signature



PS

24 May 2022 14:20 BST

British Medical Auctions
Unit 1, Sterling Centre, Eastern Road, Bracknell, RG12 2PW
Tel: +44 1252 299024
Email: enquiries@britishmedicalauctions.co.uk
Web: www.britishmedicalauctions.co.uk

British Medical Auctions
Ultrasound Equipment Quality Check (EQC)
Preventive Maintenance Service Report (PM Service)
V1.0 05.2022

7. PHOTOGRAPHIC DOCUMENTATION



Photo 133



Photo 134



Photo 135



Photo 136



Photo 137



Photo 138



Photo 139




Photo 140



Photo 141

Appendix



Photo 1



Photo 2



Photo 3




Photo 5




Photo 4




Photo 7




Photo 6




Photo 9




Photo 8




Photo 11




Photo 10




Photo 13




Photo 12




Photo 15



Photo 14




Photo 17




Photo 16



Photo 19




Photo 18



Photo 21



Photo 20



Photo 23



Photo 22




Photo 25




Photo 24




Photo 27




Photo 26




Photo 29




Photo 28




Photo 31




Photo 30




Photo 33




Photo 32




Photo 35




Photo 34



Photo 37




Photo 36




Photo 39



Photo 38



Photo 41



Photo 40




Photo 43




Photo 42



Photo 45




Photo 44




Photo 47



Photo 46




Photo 49



Photo 48



Photo 51



Photo 50



Photo 53




Photo 52




Photo 55



Photo 54



Photo 57



Photo 56




Photo 59



Photo 58




Photo 61



Photo 60




Photo 63




Photo 62




Photo 65




Photo 64




Photo 67




Photo 66




Photo 69




Photo 68



Photo 71




Photo 70



Photo 73




Photo 72



Photo 75



Photo 74



Photo 77



Photo 76



Photo 79



Photo 78




Photo 81




Photo 80




Photo 83




Photo 82



Photo 85




Photo 84



Photo 87



Photo 86



Photo 89




Photo 88




Photo 91




Photo 90




Photo 93




Photo 92




Photo 95




Photo 94



Photo 97




Photo 96



Photo 99



Photo 98



Photo 101



Photo 100



Photo 103



Photo 102



Photo 105




Photo 104



Photo 107



Photo 106



Photo 109




Photo 108




Photo 111



Photo 110




Photo 113




Photo 112




Photo 115




Photo 114



Photo 117




Photo 116




Photo 119



Photo 118



Photo 121




Photo 120




Photo 123




Photo 122



Photo 125



Photo 124



Photo 127



Photo 126



Photo 129



Photo 128




Photo 131




Photo 130



Photo 133




Photo 132




Photo 135



Photo 134



Photo 137



Photo 136



Photo 139



Photo 138



Photo 141



Photo 140

[25-05-2022 13_43 - sonosite SN 501503142.pdf](#)