



British Medical Auctions Ultrasound Equipment Quality Check (EQC) Preventive Maintenance Service Report (PM Service)

GE / Voluson E8 / E39677

Complete

British Medical Auctions

Address: Unit 1, Sterling Centre, Eastern Road, Bracknell, RG12 2PW
Tel: +44 1252 299024
Email: enquiries@britishmedicauctions.co.uk
Web: www.britishmedicauctions.co.uk

Department: Service

System has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Safe

System Type:

Ultrasound System



Photo 1

System Manufacture:

GE

Model:

Voluson E8

Serial No.:

E39677



Photo 2

Year of Manufacture:

03.2018

Lot No.:




Photo 3

Software Level:

BT18




Photo 4




Photo 5




Photo 6




Photo 7

Service Code:

719

Electrical Safety Test Asset ID:

741

Test Equipment No. (Electrical Safety Analyzer):
Rigel 288+
SN.:10M-0263

Calibration Due Date:
05.2025

Test Equipment No. (Ultrasound Phantom):
ATS Laboratories MODEL: 539
Multipurpose Ultrasound Phantom
SN.: 200493148

Date Performed

18.11.2024 11:01 CET

Performed By

MS

1. PRELIMINARY CHECKS

Power Up

Yes



Photo 8

Database Cleared (Including all Patient Data and Previous Owner Details)

Yes



Photo 9

Password Protection

No

Time and Date Check

Yes



Photo 10

2. PHYSICAL INSPECTION

Input Power

Pass




Photo 11

External I/O

Pass

Wheels and Brakes

Pass



Photo 12



Photo 13



Photo 14



Photo 15

Control Panel Movement

Pass



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20

Cables and Connectors

Pass

Shielding and Covers

Pass



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25

Console

Pass



Photo 26

Control Panel

Pass



Photo 27

Monitor Arm

Pass



Photo 28

3. CLEANING

Monitor (CRT/LCD)

Yes



Photo 29

Touch screen

Yes




Photo 30

Console

Yes



Photo 31



Photo 32



Photo 33

Keyboard

Yes



Photo 34



Photo 35



Photo 36



Photo 37

Trackball / Optical mouse

Yes



Photo 38

Probe Holder

Yes




Photo 39



Photo 40



Photo 41



Photo 42

Internal Cleaning

Yes



Photo 43



Photo 44




Photo 45



Photo 46




Photo 47



Photo 48



Photo 49



Photo 50

Filter

Yes



Photo 51

Shielding and Covers

Yes



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56

Thermal Printer Head

Yes

4. FUNCTIONAL CHECKS

Monitor

Pass




Photo 57




Photo 58




Photo 59



Photo 60




Photo 61




Photo 62

Touch Panel

Pass




Photo 63



Photo 64



Photo 65

Console

Pass



Photo 66

Keyboard

Pass




Photo 67

B-Mode

Pass



Photo 68

M-Mode

Pass



Photo 69



Photo 70

C-Mode

Pass




Photo 71

PD-Mode

Pass



Photo 72

PW-Mode

Pass




Photo 73



Photo 74

5. PROBE NO.: 1

Probe Make

GE

Probe Model

IC5-9-D

Probe Serial Number

644814WX6



Photo 75

Visual inspection

Pass

Cable

Pass



Photo 76

Lens

Fail



Photo 77




Photo 78

Probe Casing

Pass



Photo 79



Photo 80



Photo 81

Probe Casing Strain Relief

Pass



Photo 82

Connector

Pass



Photo 83



Photo 84

Connector Strain Relief

Pass



Photo 85

Lateral resolution

Pass



Photo 86

Axial resolution

Pass



Photo 87

Image benchmark

Pass




Photo 88



Photo 89

Probe passes inspection & test

No

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

No

PROBE NO.: 2

Probe Make

GE

Probe Model

C2-9-D

Probe Serial Number

381675YP8



Photo 90

Visual inspection

Pass

Cable

Pass



Photo 91

Lens

Pass



Photo 92

Probe Casing

Pass



Photo 93



Photo 94



Photo 95



Photo 96

Probe Casing Strain Relief

Pass



Photo 97

Connector

Pass



Photo 98




Photo 99

Connector Strain Relief

Pass



Photo 100

Lateral resolution

Pass



Photo 101

Axial resolution

Pass




Photo 102

Image benchmark

Pass




Photo 103



Photo 104

Probe passes inspection & test

Yes

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Yes

PROBE NO.: 3

Probe Make

GE

Probe Model

C1-5-D

Probe Serial Number

1052382WX7



Photo 105

Visual inspection

Pass

Cable

Pass



Photo 106

Lens

Pass



Photo 107

Probe Casing

Pass



Photo 108



Photo 109



Photo 110



Photo 111

Probe Casing Strain Relief

Pass



Photo 112

Connector

Pass



Photo 113




Photo 114

Connector Strain Relief

Pass



Photo 115

Lateral resolution

Pass



Photo 116

Axial resolution

Pass




Photo 117

Image benchmark

Pass




Photo 118



Photo 119

Probe passes inspection & test

Yes

Probe has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Yes

6. SUMMARY

This service has been completed in accordance with our quality procedure.
If you have any questions or concerns, please contact us on
+44 1252 299024
or email: enquiries@britishmedicalauctions.co.uk to discuss further.

System has passed performance and safety assessments and is issued as fit for use, subject to final acceptance assessment upon fit.

Safe

Date Performed:

18.11.2024 11:53 CET

Service Engineer Signature

MS
18.11.2024 11:53 CET

British Medical Auctions
Unit 1, Sterling Centre, Eastern Road, Bracknell, RG12 2PW
Tel: +44 1252 299024
Email: enquiries@britishmedicalauctions.co.uk
Web: www.britishmedicalauctions.co.uk

British Medical Auctions
Ultrasound Equipment Quality Check (EQC)
Preventive Maintenance Service Report (PM Service)

V1.0 05.2022

7. PHOTOGRAPHIC DOCUMENTATION




Photo 120



Photo 121



Photo 122



Photo 123



Photo 124

Media summary



Photo 1




Photo 2




Photo 3




Photo 4




Photo 5




Photo 6




Photo 7



Photo 8




Photo 9




Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15




Photo 16



Photo 17



Photo 18



Photo 19




Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30




Photo 31




Photo 32



Photo 33




Photo 34



Photo 35




Photo 36




Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44




Photo 45




Photo 46



Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52




Photo 53



Photo 54



Photo 55



Photo 56



Photo 57




Photo 58



Photo 59



Photo 60



Photo 61




Photo 62




Photo 63




Photo 64



Photo 65



Photo 66




Photo 67



Photo 68



Photo 69




Photo 70



Photo 71




Photo 72



Photo 73



Photo 74




Photo 75



Photo 76



Photo 77



Photo 78




Photo 79




Photo 80



Photo 81



Photo 82



Photo 83



Photo 84



Photo 85



Photo 86




Photo 87




Photo 88




Photo 89




Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95




Photo 96



Photo 97



Photo 98




Photo 99



Photo 100




Photo 101




Photo 102




Photo 103




Photo 104



Photo 105



Photo 106



Photo 107



Photo 108




Photo 109




Photo 110



Photo 111



Photo 112



Photo 113




Photo 114



Photo 115




Photo 116




Photo 117




Photo 118




Photo 119



Photo 120




Photo 121



Photo 122



Photo 123



Photo 124