



## Ultrasound Transducer Condition Report

Date Tested 9/10/2020	Carried out By – I. Rutherford				
Manufacturer – GE	Model Number – 7S				
Serial Number – 53518PD7					
Transducer Type – Matrix Array					
Date of Manufacture – January 2006					
System used to Test – GE Vivid 7					
Cable – Good					
Lens – Good					
Discolouration –Slight					
Overall Condition – Good	© British Medical Auctions				

Airscans –








## Ultrasound Transducer Condition Report

Data Tastad 0/10/2020	Counted out Duy I. Duthoutoud			
Date Tested 9/10/2020	Carried out By – I. Rutherford			
Manufacturer – GE	Model Number – M4S			
Serial Number – 1823YP4				
Transducer Type – Matrix Array				
Date of Manufacture – September 2006				
•				
System used to Test – GE Vivid 7				
Cable – Good				
Lens – Good				
Discolouration –Slight				
_				
Overall Condition – Good				

## Airscans –








## Ultrasound Transducer Condition Report

Date Tested 9/10/2020	Carried out By – I. Rutherford				
Manufacturer – GE	Model Number – 5S				
Serial Number – 51856PD3					
Transducer Type – Matrix Array					
Date of Manufacture – February 2006					
System used to Test – GE Vivid 7					
Cable – Good					
Lens – Good					
Discolouration –Slight					
Overall Condition – Good	Medical Auctions				

Airscans –



	N/A	