



## Ultrasound Transducer Condition Report

<b>Date Tested</b> 14/10/2020	<b>Carried out By</b> – I. Rutherford
<b>Manufacturer</b> – GE	<b>Model Number</b> – C1-5-D
<b>Serial Number</b> – 140599YP2	
<b>Transducer Type</b> – Convex	
<b>Date of Manufacture</b> – 2014/04	
<b>System used to Test</b> – GE Logiq S8	
<b>Cable</b> – Good	
<b>Lens</b> – Good	
<b>Discolouration</b> –Slight	
<b>Overall Condition</b> – Good	© British Medical Auctions

### Airscans –



## Ultrasound Transducer Condition Report

<b>Date Tested</b> 14/10/2020	<b>Carried out By</b> – I. Rutherford
<b>Manufacturer</b> – GE	<b>Model Number</b> – 9L-D
<b>Serial Number</b> – 113990WP6	
<b>Transducer Type</b> – Linear	
<b>Date of Manufacture</b> – December 2011	
<b>System used to Test</b> – GE Logiq S8	
<b>Cable</b> – Good	
<b>Lens</b> – Good	
<b>Discolouration</b> –Slight	
<b>Overall Condition</b> – Good	

© British Medical Auctions

### Airscans –

